

## TABLE OF CONTENTS VOLUME I

	PAGE
CHAPTER 1: SEISMIC ACTIVITY AND GEOLOGICAL BACKGROUND	
SEISMIC ACTIVITY IN TANGSHAN AND ITS SURROUNDING AREAS .....	1
OCCURRENCE OF THE TANGSHAN EARTHQUAKE FROM THE VIEW OF FAULT BLOCK MOVEMENT .....	24
GEOLOGIC-TECTONIC BACKGROUND OF THE TANGSHAN EARTHQUAKE .....	48
RELATIONSHIP BETWEEN THE ACTIVITY OF TECTONIC SYSTEMS AND THE 1976 TANGSHAN EARTHQUAKE .....	58
THE CRUSTAL DEFORMATION ASSOCIATED WITH THE TANGSHAN EARTHQUAKE .....	71
GEOMORPHOLOGIC CHARACTERISTICS IN THE BEIJING-TIANJIN-TANGSHAN AREA AND THEIR RELATION WITH TECTONIC ACTIVITY .....	85
CHAPTER 2: ENGINEERING GEOLOGY AND HYDROGEOLOGY	
SUMMARY OF ENGINEERING GEOLOGY CONDITION IN THE URBAN AREA OF TANGSHAN .....	99
ENGINEERING GEOLOGICAL CONDITIONS OF THE EAST MINING DISTRICT, TANGSHAN .....	107
CHARACTERISTICS OF HYDROGEOLOGY IN TANGSHAN DISTRICT .....	125
OUTLINE OF ENGINEERING GEOLOGICAL CONDITIONS IN TIANJIN CITY .....	134
HYDROGEOLOGICAL CHARACTERISTICS OF THE PLAIN AREA IN TIANJIN .....	146
OUTLINE OF ENGINEERING GEOLOGICAL CONDITIONS IN THE PLAIN AREA OF BEIJING .....	154
HYDROGEOLOGIC CHARACTERISTICS OF THE PLAIN AREAS IN BEIJING .....	164
CHAPTER 3: EARTHQUAKE INTENSITY	
DISTRIBUTION AND GROUND FAILURE INTENSITY DISTRIBUTION OF THE TANGSHAN EARTHQUAKE .....	171
EARTHQUAKE DAMAGE SURVEY OF ANOMALOUS AREA OF LOWER INTENSITY IN YUTIAN .....	184
GEOLOGICAL SETTINGS OF ANOMALOUS AREA OF LOWER INTENSITY IN YUTIAN .....	188
HIGH INTENSITY ANOMALY IN THE WEST OF LIAONING PROVINCE .....	205
SOME EXPERIENCE OBTAINED IN THE EARTHQUAKE INTENSITY INVESTIGATION .....	210
EARTHQUAKE INTENSITY DISTRIBUTION IN THE CITY OF TIANJIN .....	225
EARTHQUAKE DAMAGE DISTRIBUTION IN TIANJIN CITY .....	231

## TABLE OF CONTENTS VOLUME I (CONTINUED)

EARTHQUAKE INTENSITY DISTRIBUTION IN THE CITY OF BEIJING.....	241
EARTHQUAKE DAMAGE DISTRIBUTION IN THE CITY OF BEIJING.....	244
GROUND FISSURES IN THE TANGSHAN EARTHQUAKE .....	249
IDENTIFICATION OF SAND BOILS BASED ON INFRARED COLOR AERIAL PHOTOS .....	309
IDENTIFICATION OF EARTHQUAKE DAMAGE BASED ON AERIAL PHOTOS.....	316
INVESTIGATION ON DAMAGE TO GROUND SURFACE .....	327
CHAPTER 4: STRONG EARTHQUAKE MOTION OBSERVATIONS	
GENERAL ASPECTS OF STRONG-MOTION OBSERVATIONS DURING THE TANGSHAN EARTHQUAKE.....	339
THE STRONG MOTION RECORDS OF PERMANENT ACCELEROGRAPH NETWORK.....	357
MOBILE OBSERVATIONS OF AFTERSHOCKS.....	404
CHAPTER 5: SOILS AND FOUNDATIONS	
EXPLORATION INFORMATION ON THE LIQUEFIED FOUNDATION SOIL IN TANGSHAN AND ITS VICINITY .....	439
SAND LIQUEFACTION AT LIJIATUO MINE .....	478
DAMAGE TO FOUNDATIONS IN THE METROPOLITAN TIANJIN AREA.....	494
DAMAGE TO PILE FOUNDATIONS IN TIANJIN .....	507
SOME DATA ON THE EARTHQUAKE-SUBSIDENCE OF THE SOFT CLAYEY SOIL FOUNDATION.....	518
LIQUEFACTION DATA OF SANDY SOIL WITH A SMALL AMOUNT OF CLAY GRAINS IN TIANJIN .....	535
SOIL LIQUEFACTION AT LUTAI DISTRICT DURING TANGSHAN EARTHQUAKE .....	540
LIQUEFACTION DATA OF THE SATURATED SILT UNDERLYING TIANJIN PETROLEUM CHEMICAL PLANT .....	562
CHARACTERISTICS OF LIQUEFIED SANDS IN BEIJING AND ITS ADJACENT AREAS DURING TANGSHAN EARTHQUAKE .....	573
INFORMATION ON SAND LIQUEFACTION IN XIJI DISTRICT, TONG COUNTY, BEIJING .....	591

## TABLE OF CONTENTS VOLUME II

	PAGE
CHAPTER 1: CIVIL BUILDINGS	
A SURVEY OF DAMAGE TO CIVIL BUILDINGS.....	1
STATISTICS OF DAMAGE TO MULTISTORY BRICK BUILDINGS .....	9
DAMAGE TO MULTISTORY BRICK BUILDINGS AND THEIR CHARACTERISTICS .....	27
EARTHQUAKE DAMAGE TO MULTISTORY BRICK BUILDINGS AT THE YUEJIN RESIDENTIAL QUARTERS IN TANGSHAN CITY .....	143
DAMAGE TO THE XINHUA HOTEL IN TANGSHAN CITY .....	161
DAMAGE TO THE NO. 5 BUILDING OF THE FIRST GUEST HOUSE IN TANGSHAN CITY .....	174
DAMAGE TO THE OFFICE BUILDING OF THE TRAFFIC BUREAU OF THE TANGSHAN PREFECTURE.....	186
DAMAGE TO THE MAIN BUILDING OF THE GENERAL HOSPITAL OF THE KAILUAN MINING BUREAU .....	191
DAMAGE TO THE TEACHING BUILDING OF DAXIEZHUANG PRIMARY SCHOOL OF TANGSHAN CITY .....	197
EARTHQUAKE DAMAGE TO THE BIG DINING HALL AT THE MEDICAL INSTITUTE OF THE TANGSHAN COAL MINE .....	205
DAMAGE TO THE INTERIOR FRAME BUILDINGS IN THE TANGSHAN REGION.....	209
DAMAGE TO BUILDINGS WITH SHELL ROOFS IN TANGSHAN CITY.....	236
DAMAGE TO SINGLE STORY HOUSES IN URBAN AND RURAL DISTRICTS IN THE TANGSHAN AREA.....	246
PHOTOS-DAMAGE TO OLD RESIDENTIAL BUILDINGS IN TIANJIN CITY.....	270
PHOTOS-DAMAGE TO UNIT MULTISTORY BRICK DWELLING HOUSES IN TIANJIN .....	272
PHOTOS-EARTHQUAKE DAMAGE TO THE ADMISSIONS DEPARTMENT BUILDING OF TIANJIN HOSPITAL .....	273
PHOTOS-EARTHQUAKE DAMAGE TO THE TIANJIN FRIENDSHIP HOTEL.....	275
PHOTOS-DAMAGE TO MULTISTORY BUILDINGS WITH INTERIOR FRAMES IN TIANJIN .....	276
PHOTOS-EARTHQUAKE DAMAGE TO BUILDINGS FOR PHYSICAL CULTURE IN TIANJIN.....	279
PHOTOS-EARTHQUAKE DAMAGE TO CINEMAS AND THEATRES.....	282
PHOTOS-EARTHQUAKE DAMAGE TO HIGH –RISE BUILDINGS .....	285
PHOTOS-EARTHQUAKE DAMAGE TO RESIDENTIAL BUILDINGS WITH PRE-CAST PANELS IN THE BEIJING-TIANJIN AREA .....	289

## TABLE OF CONTENTS VOLUME II (CONTINUED)

PHOTOS-EARTHQUAKE DAMAGE TO MULTISTORY BRICK RESIDENTIAL BUILDINGS IN BEIJING .....	290
PHOTOS-EARTHQUAKE DAMAGE TO BEARING WOODEN SKELETON HOUSES.....	291
PHOTOS-EARTHQUAKE DAMAGE TO BLOCK BUILDINGS.....	293
CHAPTER 2: ANCIENT CHINESE BUILDINGS	
CHARACTERISTICS OF EARTHQUAKE DAMAGE TO ANCIENT BUILDINGS.....	294
EARTHQUAKE DAMAGE TO ANCIENT BUILDINGS IN THE TANGSHAN DISTRICT .....	298
DAMAGE TO ANCIENT BUILDINGS IN TIANJIN .....	309
DAMAGE TO ANCIENT BUILDINGS IN BEIJING .....	318
DAMAGE TO IMPERIAL BUILDINGS IN THE FORBIDDEN CITY, BEIJING .....	332
DAMAGE TO ANCIENT BUILDINGS IN CHENGDE .....	338
CHAPTER 3: FACTORY BUILDINGS	
DAMAGE TO BUILDINGS WITH REINFORCED CONCRETE MULTI-STORY FRAMES AT THE KAILUAN COAL MINE .....	344
DAMAGE TO SINGLE-STORY BRICK FACTORY BUILDINGS AT KAILUAN COAL MINE.....	369
DAMAGE TO THE COAL PREPARATION PLANT AT THE TANGSHAN MINE IN THE KAILUAN COAL MINE AREA .....	392
DAMAGE TO SINGLE-STORY MILL BUILDINGS OF THE METALLURGICAL INDUSTRY .....	402
EARTHQUAKE DAMAGE TO MULTISTORY FRAME FACTORY BUILDINGS AT COKING AND REFRACTORY PLANTS .....	424
DAMAGE TO POWER PLANTS IN THE TANGSHAN AREA .....	444
DAMAGE TO POWER PLANTS IN THE CITY OF TIANJIN.....	472
DAMAGE TO SUBSTATIONS IN THE TANGSHAN AREA AND THE CITY OF TIANJIN .....	486
DAMAGE TO SINGLE-STORY BUILDINGS OF THE MACHINERY INDUSTRY.....	497
DAMAGE TO MULTI-STORY PLANT BUILDINGS OF THE CHEMICAL INDUSTRY .....	532
DAMAGE TO SINGLE-STORY MILL BUILDINGS OF THE TEXTILE INDUSTRY IN TIANJIN ....	548
DAMAGE TO FLAT SLAB FLOOR STRUCTURES IN TANGSHAN CITY .....	561
DAMAGE TO THE TANGSHAN 1 <sup>ST</sup> FLOUR MILL .....	580
DAMAGE TO COLD STORAGE BUILDINGS IN THE TANGSHAN AREA AND TIANJIN CITY ...	585
EARTHQUAKE DAMAGE TO MULTISTORY REINFORCED CONCRETE RIGID FRAME MILL BUILDINGS IN TIANJIN.....	595
DAMAGE TO LIFT-SLAB STRUCTURES IN BEIJING AND TIANJIN .....	615

## TABLE OF CONTENTS VOLUME II (CONTINUED)

### CHAPTER 4: INDUSTRIAL STRUCTURES AND EQUIPMENT

EARTHQUAKE DAMAGE TO SHAFTS AND ROADWAYS IN KAILUAN .....	626
DAMAGE TO DERRICK FRAMES AND SHAFT TOWERS AT THE KAILUAN COAL MINE.....	646
DAMAGE TO COAL SILO BINS AT THE KAILUAN COAL MINE .....	673
DAMAGE TO CONVEYOR BELT CORRIDORS AND TRESTLE BRIDGES AT THE KAILUAN COAL MINE .....	707
DAMAGE TO SOME STRUCTURES AT THE IRON AND STEEL MAKING PLANT OF THE TANGSHAN IRON AND STEEL CORPORATION .....	731
DAMAGE TO STRUCTURES AT COKING PLANTS, REFRACTORY PLANTS AND CEMENT PLANTS IN TANGSHAN PREFECTURE .....	763
EARTHQUAKE DAMAGE TO POWER PLANT STRUCTURES IN THE TANGSHAN AREA .....	809
EARTHQUAKE DAMAGE TO THE ELECTRIC POWER SYSTEM AND MAIN ELECTRICAL POWER EQUIPMENT IN THE TANGSHAN AREA .....	839
EARTHQUAKE DAMAGE TO COAL-HANDLING STRUCTURES AT POWER PLANTS IN THE TANGSHAN AREA .....	851
EARTHQUAKE DAMAGE TO THE TIANJIN NO. 1 POWER PLANT AND JUNLIANGCHENG POWER PLANT .....	872
DAMAGE TO STRUCTURES, FACILITIES AND PIPELINES AT CHEMICAL PLANTS IN THE TIANJIN AREA .....	881
EARTHQUAKE DAMAGE TO VERTICAL LAND STORAGE TANKS.....	899
EARTHQUAKE DAMAGE TO WATER TOWERS .....	906
EARTHQUAKE DAMAGE TO CHIMNEYS .....	924
DAMAGE TO INDUSTRIAL INSTALLATIONS .....	940

## TABLE OF CONTENTS VOLUME III

	PAGE
<b>CHAPTER 1: RAILWAY ENGINEERING</b>	
DAMAGE TO RAILWAY ENGINEERING .....	1
<b>CHAPTER 2: HIGHWAY ENGINEERING</b>	
EARTHQUAKE DAMAGE TO ROAD SUBGRADES AND PAVEMENT IN THE TANGSHAN AREA	60
EARTHQUAKE DAMAGE TO ROAD SUBGRADES AND PAVEMENT IN TIANJIN CITY.....	70
EARTHQUAKE DAMAGE TO GIRDER BRIDGES .....	80
EARTHQUAKE DAMAGE TO ARCH BRIDGES .....	122
EARTHQUAKE DAMAGE TO THE SHENGLI BRIDGE .....	144
EARTHQUAKE DAMAGE TO THE YUEHE BRIDGE AND THE NUZHIZHAI BRIDGE .....	154
EARTHQUAKE DAMAGE TO THE SHAHE RIVER BRIDGE IN LEIZHUANG VILLAGE.....	161
EARTHQUAKE DAMAGE TO THE ZHUACUN BRIDGE.....	166
EARTHQUAKE DAMAGE TO THE LUANHE RIVER BRIDGE IN LUANXIAN COUNTY .....	175
EARTHQUAKE DAMAGE TO THE LUTAI BRIDGE .....	185
EARTHQUAKE DAMAGE TO THE HANGU BRIDGE .....	200
EARTHQUAKE DAMAGE TO THE YUJIALING BRIDGE .....	209
EARTHQUAKE DAMAGE TO THE BADAOGU BRIDGE .....	220
LIGHTLY DAMAGED BRIDGES IN THE HIGH INTENSITY EARTHQUAKE ZONE .....	231
<b>CHAPTER 3: HYDRAULIC ENGINEERING</b>	
EARTHQUAKE DAMAGE TO HYDRAULIC STRUCTURES IN THE TANGSHAN PREFECTURE ..	243
DAMAGE TO HYDRAULIC STRUCTURES IN TIANJIN CITY.....	347
EARTHQUAKE DAMAGE TO HYDRAULIC STRUCTURES IN BEIJING CITY.....	412
DAMAGE TO HYDRAULIC STRUCTURES IN LANGFANG PREFECTURE .....	425
DAMAGE TO HYDRAULIC STRUCTURES IN LUTAI RANCH .....	437
DAMAGE TO HYDRAULIC STRUCTURES AT HANGU RANCH.....	454
DAMAGE TO THE DOUHE RESERVOIR.....	472
DAMAGE TO THE BAIHE MAIN DAM AT THE MIYUN RESERVOIR.....	521

## TABLE OF CONTENTS VOLUME III (CONTINUED)

### CHAPTER 4: ENGINEERING FOR WATER TRANSPORTATION

EARTHQUAKE DAMAGE TO SEA HARBOR AWHARVES AND SHORE SLOPES .....	534
DAMAGE TO SHIP LOCKS.....	555
EARTHQUAKE DAMAGE TO DOCKS ON THE BANKS OF THE HAIHE RIVER .....	582
EARTHQUAKE DAMAGE TO BANK SLOPES AT THE MOUTH OF THE HAIHE RIVER .....	621

### CHAPTER 5: PUBLIC WORKS

DAMAGE TO WATER SUPPLY AND SEWER WORKS.....	631
DAMAGE TO THE UNDERGROUND WATER SUPPLY NETWORK IN THE TANGSHAN URBAN DISTRICT .....	649
DAMAGE TO THE SEWER SYSTEM IN THE TANGSHAN URBAN DISTRICT.....	679
DAMAGE TO 4,000 T FABRICATED PRESTRESSED CONCRETE CYLINDRICAL WATER TANKS IN TANGSHAN.....	696
DAMAGE TO GAS AND HEATING INSTALLATIONS.....	701
DAMAGE TO GAS INSTALLATIONS IN TIANJIN CITY .....	712
DAMAGE TO UNDERGROUND AIR-DEFENSE SHELTERS .....	732

### CHAPTER 6: EARTHQUAKE RELIEF AND RECONSTRUCTION OF TANGSHAN

DISASTER RELIEF AFTER THE TANGSHAN EARTHQUAKE .....	747
THE REPAIR AND RESTORATION OF THE KAILUAN COAL MINE .....	765
EARTHQUAKE RELIEF WORK IN THE TIANJIN URBAN DISTRICT.....	776
REPAIR AND RECOVERY OF THE DOUHE RESERVOIR.....	781
EMERGENCY AT THE BAIHE RIVER MAIN DAM OF THE MIYUN RESERVOIR .....	787
EMERGENCY REPAIR OF RAILWAY BRIDGES FROM BEIJING TO SHANHAIGUAN .....	792
REPAIR OF HIGHWAYS AND RELIEF TRANSPORTATION .....	806
REPAIR OF THE TANGSHAN MUNICIPAL WATER SUPPLY SYSTEM AND RECOVERY OF THE WATER SUPPLY .....	819
REPAIR OF ELECTRIC SYSTEM POWER.....	823
REPAIR OF THE POSTAL AND TELECOMMUNICATIONS SYSTEMS IN TANGSHAN.....	830
DEALING WITH EMERGENCIES AND REPAIRS FOR THE PRODUCTION TECHNOLOGY OF THE TANGSHAN STEEL AND IRON CORPORATION.....	835
REPAIRING THE CERAMIC KILNS IN TANGSHAN CITY .....	841
REBUILDING TANGSHAN .....	845

## TABLE OF CONTENTS VOLUME IV

	PAGE
CHAPTER 1: GENERAL VIEWS OF DAMAGE IN MEIZOSEISMAL AREA .....	1
CHAPTER 2 GROUND FAILURE	
GROUND FISSURES .....	13
SAND BOILS AND WATERSPOUTS .....	23
COLLAPSE AND SETTLEMENT .....	32
CHAPTER 3 CIVIL BUILDINGS	
MULTISTORY BRICK BUILDINGS .....	39
MULTISTORY INNER-FRAME BUILDINGS .....	88
MULTISTORY FRAME AND OTHER MULTISTORY CIVIL BUILDINGS .....	98
LARGE BUILDINGS .....	108
SINGLE STORY BUILDINGS IN CITIES, TOWNS AND VILLAGES .....	11
CHAPTER 4 ANCIENT BUILDINGS .....	129
CHAPTER 5 FACTORY BUILDINGS	
SINGLE STORY REINFORCED CONCRETE COLUMN MILL BUILDINGS .....	150
SINGLE STORY MILL BUILDINGS WITH BRICK COLUMNS .....	187
MULTISTORY MILL BUILDINGS .....	195
CHAPTER 6 INDUSTRIAL STRUCTURES AND FACILITIES	
TOWERS .....	214
STORAGE .....	224
CONVEYORS .....	232
WATER TOWERS .....	242
CHIMNEYS .....	250
FURNACES AND KILNS .....	267
OIL TANKS AND OTHER CONTAINERS .....	276
UNDERGROUND TUNNELS .....	287
UNDERGROUND PIPES .....	299
OVERHEAD PIPES .....	312



## TABLE OF CONTENTS VOLUME IV (CONTINUED)

POWER SUPPLY FACILITIES .....	318
OTHERS .....	334
CHAPTER 7: RAILWAY AND HIGHWAY ENGINEERING.....	341
HIGHWAY ENGINEERING .....	379
CHAPTER 8: HYDRAULIC ENGINEERING AND ENGINEERING OF WATER TRANSPORT .....	401