
(A)
Hydrate Ridge
Eel River Basin
Costa Rica
NMDS Axis 2
NMDS Axis 1
#C2693
Stress=0.13
Carbonate, n=57
Nodule, n=10
Sediment, n=13
Bottom Water, n=2
(B)
#C2693
#5471
NMDS Axis 2
NMDS Axis 1
Stress=0.13
Native Carbonate
Bottom Water
Nodule
Sediment
Transplanted Carbonate
Colonization Carbonate
Colonization Wood